10-27-04

Cofc

HARNESS, DICKEY & PIERCE, P.L.C.

ATTORNEYS AND COUNSELORS
P.O. BOX 828

OR COURIER DELIVERY ONLY

5445 CORPORATE DRIVE TROY, MICHIGAN 48098 (248) 641-1600

OT 2 6 2004

BLOOMFIELD HILLS, MICHIGAN 48303 U.S.A.

October 26, 2004

10716715

CABLE
PATENTS TROY, MICHIGAN
TELEX NO. & REPLY
287637 HARNES UR
TELEFACSIMILE
(248) 641-0270

Director of the U.S. Patent and Trademark Office P. O. Box 1450 Alexandria, VA 22313-1450

Re:

U.S. Patent No. 6,797,907 6 lssued: September 28, 2004 Inventors: James Meagher et al. For: Rotary Switch Assembly

Certificate
OCT 2 9 2004

of Correction

Sir:

In proofreading the above identified application, the following errors were noted which appear to require a Certificate of Correction:

Column 5, line 28, claim 5 (application page 12, line 5, claim 5), after "the" insert -- button--.

Column 5, line 33, claim 7 (application page 12, line 9, claim 7), "guiding" should be --moves--.

Column 5, line 33, claim 7 (application page 12, line 9, claim 7), after "from" insert - the--.

Column 6, line 36, claim 19 (application page 16, line 8, claim 21), after "conductors" insert --is--.

Column 6, line 41, claim 21 (application page 16, line 13, claim 23), after "conductors" insert --is--.

Column 6, line 53, claim 22 (amendment dated 5/18/04, page 8, line 11, claim 24), "conductors" should be --conductor--.

Director of the U.S. Patent and Trademark Office Page 2 October 26, 2004

Enclosed herewith is an original and a copy of the Patent and Trademark Office Certificate of Correction form which we request be approved for the above identified patent.

The Director is hereby authorized to charge any additional fees which may be required in connection with this correction to Deposit Account No. 08-0750. A duplicate copy of this letter is enclosed.

Respectfully submitted,

Michael P. Brennan

Reg. No. 30,612

MPB/rc Enclosure

HARNESS, DICKEY & PIERCE, P.L.C.

ATTORNEYS AND COUNSELORS
P.O. BOX 828

FOR COURIER DELIVERY ONLY

5445 CORPORATE DRIVE TROY, MICHIGAN 48098 (248) 641-1600 OT 2 6 2004 6

LOOMFIELD HILLS, MICHIGAN 48303 U.S.A.

October 26, 2004

CABLE
PATENTS TROY, MICHIGAN
TELEX NO. & REPLY
287637 HARNES UR
TELEFACSIMILE
(248) 641-0270

Director of the U.S. Patent and Trademark Office P. O. Box 1450 Alexandria, VA 22313-1450

Re:

U.S. Patent No. 6,797,907 & 1 Issued: September 28, 2004 Inventors: James Meagher et al. For: Rotary Switch Assembly

Sir:

In proofreading the above identified application, the following errors were noted which appear to require a Certificate of Correction:

Column 5, line 28, claim 5 (application page 12, line 5, claim 5), after "the" insert -- button--.

Column 5, line 33, claim 7 (application page 12, line 9, claim 7), "guiding" should be --moves--.

Column 5, line 33, claim 7 (application page 12, line 9, claim 7), after "from" insert - the--.

Column 6, line 36, claim 19 (application page 16, line 8, claim 21), after "conductors" insert --is--.

Column 6, line 41, claim 21 (application page 16, line 13, claim 23), after "conductors" insert --is--.

Column 6, line 53, claim 22 (amendment dated 5/18/04, page 8, line 11, claim 24), "conductors" should be --conductor--.

Director of the U.S. Patent and Trademark Office Page 2 October 26, 2004

Enclosed herewith is an original and a copy of the Patent and Trademark Office Certificate of Correction form which we request be approved for the above identified patent.

The Director is hereby authorized to charge any additional fees which may be required in connection with this correction to Deposit Account No. 08-0750. A duplicate copy of this letter is enclosed.

Respectfully submitted,

Micbael P. Brennan

Reg. No. 30,612

MPB/rc Enclosure

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO:

6,797,907 B1

DATED:

September 28, 2004

INVENTOR(S):

James Meagher et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 5,

line 28, after "the" insert --button--. line 33, "guiding" should be --moves--. line 33, after "from" insert --the--.

Column 6,

line 36, after "conductors" insert --is--. line 41, after "conductors" insert --is--. line 53, "conductors" should be --conductor--

MAILING ADDRESS OF SENDER:

Michael P. Brennan, Esq. Harness, Dickey & Pierce, P.L.C.

P.O. Box 828

Bloomfield, MI 48303

PATENT NO. 6,797,907

No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO:

6,797,907 61

DATED:

September 28, 2004

INVENTOR(S):

James Meagher et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 5,

line 28, after "the" insert --button--. line 33, "guiding" should be --moves--. line 33, after "from" insert --the--.

Column 6,

line 36, after "conductors" insert --is--.
line 41, after "conductors" insert --is--.
line 53, "conductors" should be --conductor--

MAILING ADDRESS OF SENDER:

Michael P. Brennan, Esq. Hamess, Dickey & Pierce, P.L.C. P.O. Box 828 Bloomfield, MI 48303

PATENT NO. __6,797,907

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.



October 26, 2004

Director of the U.S. Patent and Trademark Office P. O. Box 1450 Alexandria, VA 22313-1450

Re:

Patent No. 6,797,907 131

Issued: September 28, 2004 Inventor(s): James Meagher et al. Rotary Switch Assembly

Sir:

We have noted in proofreading Patent No. 6,797,907 the following errors:

On the Title Page, No. (57), Abstract (application page 18, line 5), after "circuit" insert --board--.

Column 2, line 33 (application page 4, line 8, second occurrence), after "least" delete "of".

Column 3, line 30 (application page 6, line 13), "peferably" should be --preferably--.

Kindly make these errors of record in your files.

nael P. Brennan

ég. No. 30,612

MPB/rc

5445 Corporate Drive, Suite 400, Troy, MI 48098

Phone 248.641.1600

Fax 248.641.0270

atent No. 6,797,907

tforney Docket No. 5060-000136

Express Mail Label No. EV 406 076 459 US (10/26/2004)

Certificate of Mailing under 37 CFR 1.8

I hereby certify that this correspondence is being deposited with the United States Postal Service with sufficient postage as express mail in an envelope addressed to:

> Director of the United States Patent and Trademark Office P.O. Box 1450 Alexandria, VA 22313-1450

on October 26, 2004

Date

Signature

Michael P. Brennan

Typed or printed name of person signing Certificate

Note: Each paper must have its own certificate of mailing, or this certificate must identify each submitted

paper.

Submitted herewith is (are):

Certificate of Correction Transmittal (in duplicate)

Certificate of Correction Form PTO/SB/44 (in duplicate)

Errors of Record

Return Postcard